

DELHI JAL BOARD: DELHSARKAR
OFFICE OF THE EXECUTIVE ENGINEER (SOUTH)-I
OPPOSITE J-BLOCK MARKET SAKET, NEW DELHI-110017.

NO. EE(S)-I / F-9 / 2014 / 2670-2675

DT: 8/7/2014

Minutes of meeting held on 13/6/14 with RWA C-8 and C-9 Vasant Kunj

Following were Present :-

1. Shri Anil Kr. Sharma - Executive Engineer (S)-I
2. Shri Sudhir Sangal - Zonal Engineer (S)
3. Shri Anoop Goel - Junior Engineer (S)
4. Smt. Indu Gahlot President -C-9 Block
5. Smt Preeti Secretary -C-9 Block
6. Shri Mahajan -Resident C-9 Block

The following issues were discussed:

1.	Sewer Overflow from House no. 9647 to 9670.	It was informed by RWA that there is over flow of sewer in some of the houses , during rainy season. It is further informed by RWA that it is due to back flow of sewer from C-6 Block there is overflow of sewer in C-9. Z.E has been directed to provide technical feasible solution to avoid over flow of sewer during rainy season. Action – Z.E Shri Sudhir Sangal -J.E Shri Anoop
2.	Drop Box at C-9 for water bill payment.	It was informed by RWA that they are facing problem in depositing the water bills at ZRO office. They requested to provide a drop box at C-9. Zonal Revenue Officer has been asked to do so. Action- ZRO, Vasant Kunj
3.	Inflated Bill	It was informed by RWA that some of the residents are getting inflated bill . ZRO has been asked to check the bills and correct them if inflated. RWA has also been asked to provide K No of such cases. Action- ZRO , Vasant Kunj
4.	No filter water from House NO. 9296 to 9390.	It is informed by RWA that from House NO. 9296 to 9390 are not getting filtered water. They are dependent on tube well supply. Direction is issued to concerned Z.E & J.E to check the technical feasible solution as early as possible. . Action – Z.E- Shri T.C. Suneja -J.E. Shri Anoop

All Concerned


Executive Engineer (S)-I

Copy for information to :-

1. C.E (S)
2. S.E (S)


Executive Engineer (S)-I

**DELHI JAL BOARD: DELHSARKAR
OFFICE OF THE EXECUTIVE ENGINEER (SOUTH)-I**

OPPOSITE J-BLOCK MARKET SAKET, NEW DELHI-110017.

MO:- EEBDI/F-9/2014/2676-2687 dt: 8/7/2014

Minutes of meeting held on 28/6/14 with Federation of RWAs Vasant Kunj
Following were Present :-

1. Shri Anil Kr. Sharma - Executive Engineer (S)-I
2. Shri T.C. Suneja - Zonal Engineer (S)
3. Shri Anoop Goel - Junior Engineer (South)
4. Shri Bhanu Bishnoi - Chairman Federation of RWA
5. Smt Jyoti Chanana - (President) B-8 block Vasant Kunj
6. Smt Meenakshi - (President) B-7 block Vasant Kunj
7. Smt Sushila Kakkar - Gen Secy B-2 RWA
8. Shri S.P. Wadhwa - Treasurer B-2 Block Vasant Kunj
9. Shri Satpal Singh Wadhwa - B-2, Vasant Kunj
10. Shri H.S. Bawa - B-2/2364 Vasant Kunj
11. Shri P.R Taneja - Gen Secy. D-4 block
12. Shri Sudhir Chandela - C-3 RWA
13. Shri G. Adhikari - Estate Officer RWA B-10 Vasant Kunj

The following issues were discussed:

1.	Cover of ferrule chamber and common sewer chamber to be replaced	It was informed by RWA that the cover of ferrule chamber and common sewer chamber needs to be replaced. It is apprised to them that it will be replaced in phase manner wherever required. Direction for framing the estimate has been given to concerned Zonal Engineer. Action - Z.E Shri T.C. Suneja -Z.E Shri Sudhir Sangal
2.	Requirement of sewer cleaning in B-10 and C-3 Block Vasant Kunj	It was informed by RWA that in B-10 & C-3 Block there is requirement of sewer cleaning. It was informed that in B-10 sometimes there is overflow of sewer. Direction is issued to concerned Z.E to clean the sewer lines and manholes as early as possible. Action-ZE, Shri Sudhir Sangal
3.	List of registered plumber to be made available to RWA	It was informed by RWA that List of registered plumber is not available with them, it should be made available. Direction is being issued to ZRO to provide the list of registered plumber to RWA and display in their office. Action- Z.R.O. Vasant Kunj
4.	Abandoned tube well room to be demolished or to be handed over to the RWA	It was requested by RWA to hand over the tube well room to RWA or to dismantle the same. It was apprised to them most of the abandoned tube-well rooms have been demolished. Very few have been left wherever RWA has objection. It is apprised to them that the balance

		will be also demolished in due course of time. Regarding handing over to RWA it is informed that this is a policy matter which is yet to be decided. Action: ZE Sh. T. C. Suneja
5	Filter water supply is not coming in 36 flats of B-2 block Vasant Kunj	It was informed by RWA that filter water is not coming in B-2 Block, 36 flats. They are getting water through tube well and tankers. They have also informed that the discharge of tube well has substantially reduced and they are facing crisis of water. Z.E & J.E are directed to provide technical feasible solution as early as possible. Action- Z.E Shri T.C. Suneja J.E Shri Anoop
6	Installation of water meter of unmetered/ non-working connections	It was informed by RWA that water meter should be installed on all unmetered/ non-working meter connections. ZRO has been asked to provide the list of unmetered and non-working metered connections. RWA has also been asked to provide such list. Action: ZRO(SW)II, RWAs
7	Circular for cost of the water	RWA has informed that they are not aware of the charges of cost of water. It has been apprised to them that circular regarding cost of water will be provided to them. RWAs have advised not to use DJB water for any construction purpose. Action: ZRO(SW)II, RWAs
8.	Overflow of water from individual tank	RWA has informed that there is overflow of water from some of the individual tanks. RWAs have been requested to educate residents and provide list of such flats. ZE has also been directed to issue notice and challans to such flat owners. Action: ZE Sh. T. C. Suneja, RWAs

All Concerned

Copy for information to :-

1.C.E (S)

2.S.E (S)


Executive Engineer (S)-I


Executive Engineer (S)-I

DELHI JAL BOARD: DELHSARKAR
OFFICE OF THE EXECUTIVE ENGINEER (SOUTH)-I
OPPOSITE J-BLOCK MARKET SAKET, NEW DELHI-110017.

NO: EE (S)-I/DJB) 4484

Dated: 10/10/2014

Minutes of meeting held with RWA of Pocket C-9, Vasant Kunj on dated 9/10/2014

Following were Present :-

1. Shri L.L.Meena - Executive Engineer (S)-I, (M- 9650191590)
2. Shri Sudhir Sangal - Zonal Engineer (S)-I (M-9650291417)
3. Shri T.C. Suneja - Zonal Engineer (S) -I (M-9650291180)
4. Shri Anoop Goel - Junior Engineer (S)-I (M-9650094189)
5. Smt. Indu Gahlot President -C-9 Block (M-9810028395)
6. Shri Devinder Singh Yadav -ASI, D.J.B (M- 9650291410)

The following issues were discussed:

1.	Overflow of water through storage tank of Consumer	It was pointed out by Member of RWA that they were noticed over flow of drinking water through consumers storage tank during supply hours in C-9. And requested to take necessary action/measures . In this regard it was apprised that notice / challans were being issued to defaulter. RWA's member was also appreciated the action being taken by the DJB. Action by - Shri T.C. Suneja, Z.E / Shri Anoop ,J.E
2.	Diversion of sewer line from C-6 to C-9 .	It was pointed out by the Member of RWA that during the rainy season, overflow of sewage noticed at C-9 pocket, and needs to diversion of sewer line. It was apprised that the mentioned locations / flats are under preview of DDA and action to be taken by them. However, DJB will fix up joint visit with the DDA officials along with RWA to take necessary measures with 15 days. At present, no overflow through the DJB sewer line. The action to diversion of the sewage load from C-6 to C-9 shall be taken after explore the technical feasibility. The survey work will be completed within 15 days Action by - Shri Sudhir Sangal, Z.E / Shri Anoop ,J.E
3.	Adjustment of filter eater supply to ensure equitability distribution of water in C-9 Vasant Kunj	It was informed by member of the RWA that there is scarcity of filtered water from Flat no. 9300 to 9388 . However, tube well water supply is available . They are requesting to ensure equitability distribution of filtered water supply by adjustment of sluice valve. In this regard , directions were issued to concerned Z.E/ J.E to do the needful. Action by - Shri T.C. Suneja, Z.E / Shri Anoop ,J.E

Meeting ended with vote of thanks to the chair.

All Concerned


Executive Engineer (S)-I

dc

DELHI JAL BOARD: DELHSARKAR
OFFICE OF THE EXECUTIVE ENGINEER (SOUTH)-I
OPPOSITE J-BLOCK MARKET SAKET, NEW DELHI-110017.

NO: EE (S)-I/DJB) 4484

Dated: 10/10/2014

Minutes of meeting held with RWA of Pocket C-9, Vasant Kunj on dated 9/10/2014

Following were Present :-

1. Shri L.L.Meena - Executive Engineer (S)-I, (M- 9650191590)
2. Shri Sudhir Sangal - Zonal Engineer (S)-I (M-9650291417)
3. Shri T.C. Suneja - Zonal Engineer (S) -I (M-9650291180)
4. Shri Anoop Goel - Junior Engineer (S)-I (M-9650094189)
5. Smt. Indu Gahlot President -C-9 Block (M-9810028395)
6. Shri Devinder Singh Yadav -ASI, D.J.B (M- 9650291410)

The following issues were discussed:

1.	Overflow of water through storage tank of Consumer	It was pointed out by Member of RWA that they were noticed over flow of drinking water through consumers storage tank during supply hours in C-9. And requested to take necessary action/measures . In this regard it was apprised that notice / challans were being issued to defaulter. RWA's member was also appreciated the action being taken by the DJB. Action by - Shri T.C. Suneja, Z.E / Shri Anoop ,J.E
2.	Diversion of sewer line from C-6 to C-9 .	It was pointed out by the Member of RWA that during the rainy season, overflow of sewage noticed at C-9 pocket, and needs to diversion of sewer line. It was apprised that the mentioned locations / flats are under preview of DDA and action to be taken by them. However, DJB will fix up joint visit with the DDA officials along with RWA to take necessary measures with 15 days. At present, no overflow through the DJB sewer line. The action to diversion of the sewage load from C-6 to C-9 shall be taken after explore the technical feasibility. The survey work will be completed within 15 days Action by - Shri Sudhir Sangal, Z.E / Shri Anoop ,J.E
3.	Adjustment of filter eater supply to ensure equitability distribution of water in C-9 Vasant Kunj	It was informed by member of the RWA that there is scarcity of filtered water from Flat no. 9300 to 9388 . However, tube well water supply is available . They are requesting to ensure equitability distribution of filtered water supply by adjustment of sluice valve. In this regard , directions were issued to concerned Z.E/ J.E to do the needful. Action by - Shri T.C. Suneja, Z.E / Shri Anoop ,J.E

Meeting ended with vote of thanks to the chair.

All Concerned


Executive Engineer (S)-I

dc

**DELHI JAL BOARD: DELHSARKAR
OFFICE OF THE EXECUTIVE ENGINEER (SOUTH)-I
OPPOSITE J-BLOCK MARKET SAKET, NEW DELHI-110017.**

NO: DTB/EE(S)-I/2014/5117

Dated: 20-10-2014

Minutes of meeting held with RWA of Pocket B-7 & B-8 Vasant Kuni on dated 18/10/2014

Following were Present :-

1. Shri L.L.Meena - Executive Engineer (S)-I, (M- 9650191590)
2. Shri Sudhir Sangal - Zonal Engineer (S)-I (M-9650291417)
3. Shri T.C. Suneja - Zonal Engineer (S) – I (M-9650291180)
4. Shri Anoop Goel - Junior Engineer (S)-I (M-9650094189)
5. Smt. Jyoti Channa -President -B-8 Block (M-9711298878)
6. Smt. Meenakshi Kuma , President –B-7 (M-9810328538)
7. Shri Devender Yadav -ASI, D.J.B (M- 9650291410)

The following issues were discussed:

1.	Overflow of water from Water tanks	<p>It was pointed out by both Member of RWAs that they were noticed over flow of drinking water tank during supply hours in B-7 & B-8 Vasant Kunj. However RWAs were issued advisory circular to stop the wastage of precious potable water through overflow of water tank but no one bothered about it. They were requested to take necessary action against defaulters. and RWA will also assistance. in this regard, directions were issued to the concerned Z.E /J.E to I conduct the survey during the supply hours and issue notice /challan and submit action taken report within a week .Further, also directed to keep drive of challan in interval of a month to avoid the wastage of water through the consumers water tank.</p> <p>Action by – Shri T.C. Suneja, Z.E / Shri Anoop ,J.E</p>
2.	Regarding Ferrule chamber cover	<p>It was pointed out by both Member of RWA about damages of ferrule chambers which may be cause of accident . In this regard, it was decided that joint visit along with RWAs will conduct and prepare a list of such ferrule chambers on which cover is required. If covers are repairable, do needful otherwise prepare the estimate for providing fixing ferrule chamber. The action taken report should be completed within two weeks.</p> <p>Action by - Shri T.C. Suneja , Z.E / Shri Anoop ,J.E</p>
3.	Common chamber cover/frame	<p>It was informed by both member of the RWAs that some cover/frame are damaged and need to replace . It was decided that Z.E /J.E (Sewer) will conduct survey of B-7 & B-8 along with member of RWA to identify missing /damaged cover frame of common chamber. and take necessary action.</p> <p>Action by – Shri Sudhir Sangal , Z.E / Shri Anoop ,J.E</p>
4	Sewer manhole cover/frames	<p>It was informed that some sewer manhole cover/frames are damaged and need to be replaced. Concerned Z.E /J.E (Sewer) were directed to replace the same within 24 hours in consult with the RWA. Further, advise to member of RWA that any complaints related to sewer and water may be lodged on CCR Number- 1916(toll free)so that timely action could be ensured .</p> <p>Action by – Shri Sudhir Sangal , Z.E / Shri Anoop ,J.E</p>

DELHI JAL BOARD: DELHSARKAR
OFFICE OF THE EXECUTIVE ENGINEER (SOUTH)-I
OPPOSITE J-BLOCK MARKET SAKET, NEW DELHI-110017.

NO: DTB/EE(S)-I/2014/5117

Dated: 20-10-2014

Minutes of meeting held with RWA of Pocket B-7 & B-8 Vasant Kuni on dated 18/10/2014

Following were Present :-


1. Shri L.L.Meena - Executive Engineer (S)-I, (M- 9650191590)
2. Shri Sudhir Sangal - Zonal Engineer (S)-I (M-9650291417)
3. Shri T.C. Suneja - Zonal Engineer (S) – I (M-9650291180)
4. Shri Anoop Goel - Junior Engineer (S)-I (M-9650094189)
5. Smt. Jyoti Channa -President -B-8 Block (M-9711298878)
6. Smt. Meenakshi Kuma , President –B-7 (M-9810328538)
7. Shri Devender Yadav -ASI, D.J.B (M- 9650291410)

The following issues were discussed:

1.	Overflow of water from Water tanks	It was pointed out by both Member of RWAs that they were noticed over flow of drinking water tank during supply hours in B-7 & B-8 Vasant Kuni. However RWAs were issued advisory circular to stop the wastage of precious potable water through overflow of water tank but no one bothered about it. They were requested to take necessary action against defaulters. and RWA will also assistance. in this regard, directions were issued to the concerned Z.E /J.E to I conduct the survey during the supply hours and issue notice /challan and submit action taken report within a week .Further, also directed to keep drive of challan in interval of a month to avoid the wastage of water through the consumers water tank. Action by – Shri T.C. Suneja, Z.E / Shri Anoop ,J.E
2.	Regarding Ferrule chamber cover	It was pointed out by both Member of RWA about damages of ferrule chambers which may be cause of accident . In this regard, it was decided that joint visit along with RWAs will conduct and prepare a list of such ferrule chambers on which cover is required. If covers are repairable, do needful otherwise prepare the estimate for providing fixing ferrule chamber. The action taken report should be completed within two weeks. Action by - Shri T.C. Suneja , Z.E / Shri Anoop ,J.E
3.	Common chamber cover/frame	It was informed by both member of the RWAs that some cover/frame are damaged and need to replace . It was decided that Z.E /J.E (Sewer) will conduct survey of B-7 & B-8 along with member of RWA to identify missing /damaged cover frame of common chamber. and take necessary action. Action by – Shri Sudhir Sangal , Z.E / Shri Anoop ,J.E
4	Sewer manhole cover/frames	It was informed that some sewer manhole cover/frames are damaged and need to be replaced. Concerned Z.E /J.E (Sewer) were directed to replace the same within 24 hours in consult with the RWA. Further, advise to member of RWA that any complaints related to sewer and water may be lodged on CCR Number- 1916(toll free)so that timely action could be ensured . Action by – Shri Sudhir Sangal , Z.E / Shri Anoop ,J.E

5	Leakage in 450 mm dia PSC water line near B-7/5022	<p>It was pointed by member of the RWA regarding frequent leakages in 450 mm dia PSC water line near B-7/5022 . In this regard, it was intimated that estimate has been approved and tenders were being invited . The work will be completed by the end of Feb. 2011. Meanwhile, leakages have been repaired temporary. Further, also apprised to the member of the RWA that a comprehensive scheme for replacement of 450 mm dia PSC peripheral water line has been prepared and in process for approval.</p> <p>Action by – Shri Sudhir Sangal , Z.E / Shri Anoop ,J.E</p>
---	--	--

Meeting ended with vote of thanks to the chair.



All Concerned

Executive Engineer (S)-I

DELHI JAL BOARD: DELHSARKAR
OFFICE OF THE EXECUTIVE ENGINEER (SOUTH)-I
OPPOSITE J-BLOCK MARKET SAKET, NEW DELHI-110017.

NO:- EE (S)-I / DTB / 2014 / 5333

Dated: 12-11-14

Minutes of meeting held with RWA of Pocket C-1, Vasant Kunj on dated 10/11/2014

Following were Present :-

1. Shri L.L.Meena - Executive Engineer (S)-I, (M- 9650191590)
2. Shri Sudhir Sangal - Zonal Engineer (S)-I (M-9650291417)
3. Shri T.C. Suneja - Zonal Engineer (S) – I (M-9650291180)
4. Shri Anoop Goel - Junior Engineer (S)-I (M-9650094189)
5. Shri Anil Aggarwal -President -C-I Block (M-9811055333)
6. Shri K.L. Sehgal -Member -C-I ,RWA (M- 9911481558)

The following issues were discussed:

1.	Rusting of water line	It was pointed out by Shri Aggarwal that there is a chance of rusting of C.I water line which was laid by DDA long period ago. It is decided that a piece of the existing pipe line will be cut in presence of member of the RWA to check the condition of rusting of the pipe inner side in course of the time within 3 days. and thereafter technical viable will be explored . Action by – Shri T.C. Suneja, Z.E / Shri Anoop ,J.E
2.	Repairing/replacement of the common chamber	It was informed by member of the RWA that some common chamber are in damaged and need to be repair . Damage cover manhole are also to be replaced. It is decided that a detailed survey will be carried out by concerned J.E/Z.E and take necessary action. Action by - Shri Sudhir Sangal, Z.E / Shri Anoop ,J.E
3.	Regarding buried /non traceable manhole	It was informed by Shri Aggarwal that due to non visible of some manhole covers, it is difficult to take quick action on account of removal of sewer blockage if any in future. and DJB ensure that all buried manhole covers should be visible. Concerned Z.E/J.E directed to ensure it in time bound manner. Action by – Shri T.C. Suneja, Z.E / Shri Anoop ,J.E
4	Over flow of water through consumers tanks	All members of RWA were pointed out regarding overflow of potable water through consumers tank. In this regard it is decided that first of all notice should be issued to the all residents with advise to take measures to stop overflow of the potable water. In case of non compliance of the advise, DJB is bound to issue court challan for penalize the defaulter. It was informed by EE (S)-I that notice will be served within a week and thereafter challan will be issued against the defaulter.
5	Turbidity / contamination of the water supply	It was pointed out by Shri Sehgal that there is a chance of turbidity, bad taste and contamination at their residence since two days. Shri Anoop J.E apprised that water sample had been taken in presence of his wife and found there was no water contamination. The residual chlorine in the water was also present. The quick action taken by the DJB was also appreciated by all Members. Further, advised to tall Members that publicity should be done

	<p>amongst the residents to lodge the complaint related to water & sewer on CCR number -1916 (toll free) so that time bound action may be taken.</p> <p>Action by – Shri T.C. Suneja, Z.E / Shri Anoop, J.E</p>
--	---

Meeting ended with vote of thanks to the chair.

All Concerned

(Signature)
Executive Engineer (S)-I

<p>...</p>	<p>...</p>
<p>...</p>	<p>...</p>
<p>...</p>	<p>...</p>
<p>...</p>	<p>...</p>
<p>...</p>	<p>...</p>

DELHI JAL BOARD: DELHSARKAR
OFFICE OF THE EXECUTIVE ENGINEER (SOUTH)-I
OPPOSITE J-BLOCK MARKET SAKET, NEW DELHI-110017.

NO. EEC(S)-I/DJB/2014/5610

Dated: 18/11/2014

Minutes of meeting held with RWA Harijan Basti Masood Pur , on dated 15/11/2014

Following were Present :-

1. Shri L.L.Meena - Executive Engineer (S)-I (M-9650191590)
2. Shri Sudhir Sangal - Zonal Engineer (S)-I (M-9650291417)
3. Shri Anoop Goel - Junior Engineer (S)-I (M-9650094189)
4. Shri Bhagwati Singh - RWA Member (M-9650624643)
5. Shri Suraj Pal - RWA Member (M-996852639)
6. Shri Virender - Vice President RWA (M-8800545497)
7. Shri Jeet Singh - President RWA (M-9910078945)

The following issues were discussed:

1.	Boring of tube well	It was pointed out by the President of RWA that there is a scarcity of water in Masoodpur Harijan Basti . They are pursuing the issue with the DJB since long time but no action taken on augmentation of the water supply either filtered or tube well. In this regard, it was informed to the RWA that a case for installation of bore well has been permitted by the Advisory committee. And same will be installed shortly. Thereafter , water supply in short fall area will be improved. Action by – Shri T.C. Suneja, Z.E / Shri Anoop ,J.E
2.	Sewerage system	It was appreciated by the member of RWA that sewerage system is functioning well but needs to desilt the manholes to avoid chance of blockage of the sewer. In this regard, directed to concerned Z.E /J.E that they will ensure it within a month . Action by – Shri Sudhir Sangal , Z.E / Shri Anoop ,J.E

Meeting ended with vote of thanks to the chair.

All Concerned


Executive Engineer (S)-I

DELHI JAL BOARD: DELHSARKAR
OFFICE OF THE EXECUTIVE ENGINEER (SOUTH)-I
OPPOSITE J-BLOCK MARKET SAKET, NEW DELHI-110017.

Minutes of meeting held with RWA Duggal colony on dated 9/1/2015

Following were Present :-

1. Shri L.L.Meena - Executive Engineer (S)-I, (M- 9650191590)
2. Shri R.B. Sharma - Zonal Engineer (S)-I (M-9650108922)
3. Shri Khalid Husain - Junior Engineer (S)-I (M-9650291486)
4. Shri R.K. Sharma - Treasurer (M-9213962614)
5. Ms. Seema Singh - Gen. Secretary (M-9999519988)
6. Shri M.S. Tyagi - President (M-8743880001)


The following issues were discussed:

1.	Repair of leakage and Replacement of old/damaged water distribution system	It was pointed out by the Member of RWA that after connecting old system with the peripheral water line, water supply of Duggal colony definitely improved but so many leakages noticed in old system. It was informed to the RWA that the existing system was laid 20 years ago in which water supply from the tube wells was available. Now, Duggal colony has connected with the filter water supply and accordingly water supply as well as pressure improved. DJB is already taking seriously action to repair the leakages as noticed and most of leakages have been repaired. However, RWA is requested to intimate about the leakages whenever noticed. Further, it was also informed that a proposal for replacement of old/ damaged water lines wherever necessary in Duggal colony has been framed and in process for approval. Action by -Z.E /J.E
2.	Rationalization of water supply	It was pointed out by Member of RWAs that there is need to rationalize the available water supply so that water could be made available to each street in Duggal colony with proper quantity. In this regard, it was decided that a joint visit will be carried out along with the RWA to identify short supply area /location during the supply hours and thereafter suitable action will be taken. Further, it was also intimated that at present filter water supply is available on Tuesday and Friday in a week from the ESI BPS command area according to availability of water. Action by -Z.E /J.E
3.	Regularization of U/A water connection and action against defaulters	It was pointed out by Member of RWA that water supply has been improved and needs to ensure regularization of the unauthorized water connection and also take action against defaulters. In this regard, directions will be issued to the Zonal Revenue Officer to identify the U/A water connections in the area and take action as per DJB Act. RWA is requested to cooperate in this regard. Action by - Z.R.O(S)-I/ Z.E /J.E
4.	Water scarcity in Lane A-90 and A-87 Duggal Colony and Water scarcity in lane of A-73 and connect the tube well supply with the system	Ms. Seema Singh pointed out to scarcity of water in lane A-90 to A-87 Duggal Colony. It is decided that Joint visit will be carried out along with RWA and taken appropriate action within a week Action by -Z.E /J.E

Z.E - JV
Dy. No. 3308
13-1-15

Meeting ended with vote of thanks to the chair.

All Concerned


(R.B. Sharma)
Zonal Engineer (S)-I

DELHI JAL BOARD: DELHSARKAR
OFFICE OF THE EXECUTIVE ENGINEER (SOUTH)-I
OPPOSITE J-BLOCK MARKET SAKET, NEW DELHI-110017.

Minutes of meeting held with RWA RPS Flats on dated 2/2/2015

Following were Present :-

1. Shri L.L.Meena - Executive Engineer (S)-I, (M- 9650191590)
2. Shri R.B. Sharma - Zonal Engineer (S)-I (M-9650108922)
3. Shri Khalid Husain - Junior Engineer (S) -I (M-9650291486)
4. Shri A.N. Aggarwal - Cashier RWA (M-9210584530)
5. Ms. Rajni Kurra - Gen. Secretary RWA (M-9560012343)
6. Shri Sunil Hadkan - Joint Secy RWA (M-9555124455)


The following issues were discussed:

1.	Reboring of tube wells	Member of RWA has desired to make rebore in lieu of dried up tube well to improve the water supply at the tail end where remains scarcity of filtered water. It was informed that a proposal has been framed and in process for approval. Action by -Z.E /J.E
2.	Frequent leakages & water contamination from House no. 235 to 304	As inform by the Member of RWA that frequent leakages /contamination noticed from House no. 235 to 304 and needs to take action. It was informed by the concerned Z.E /J.E that contamination was due to rusted / damaged service pipes of the consumer and same has been rectified. Action by -Z.E /J.E
3.	Repair of booster pump	It was pointed out by Member of RWA that the condition of the existing booster pump is very bad and require repairing. It was directed to J.E/ Z.E to frame the proposal and put up in next financial year. Action by -Z.E /J.E
4.	Replacement of old water lines	As informed by Member of RWA that the existing water distribution system is very old and needs to replacement. In this regard, concerned J.E apprised that due to extension of the existing building portion, no space available to lay water line. Further, it was decided that a joint visit will be carried out along with the RWA to identify the feasibility for laying of water line and after that action will be taken accordingly. Action by -, Z.E /J.E
5.	Replacement of sewer line	As informed by the Member of RWA , that existing sewerage system is very old and needs replacement. For this, concerned Z.E (Sewer) will conduct the survey of the colony and thereafter he will put up the proposal if technically required. Action by -, Z.E (Sewer) /J.E (Sewer)

Z.E - IV
Dy. No. 3537
Dated 2/2/15

Meeting ended with vote of thanks t to the chair.

All Concerned


R.B. Sharma

Zonal Engineer (S)-I